



Ness LLC

1315 W. Orchard Ave, Nampa, ID 83651
phone 208.466.7594 - fax 208.461.9505 - RCE-481
email: doug@nessllc.com - www.nessllc.com



Ness LLC Proposal for: 7910 W. Tarp Dr. Boise, Idaho 83709

April 16, 2020

What to expect with Mold Remediation????


- ✓ Access is key! We will need admission Monday through Friday, 8 am - 5 pm while the project is in progress. Ness is bonded and insured. It is not necessary for a home owner to be present while the work is being done. Please make sure we have a house key or garage code for entry. **The easier the access is for our technicians, the faster the job goes!**

- ✓ All access to the crawlspace will be protected by plastic sheeting during work.

- ✓ Fans need time to dry the area. We don't always schedule for consecutive days. We try to give as much notice as possible but last minute schedule changes can and do occur. Please direct any questions you have to requests@nessllc.com

- ✓ **Please note:** If a signed contract is returned within 24 hours, your estimated start date will be some time during the week of April 27th. Please plan accordingly. If there are any cancellations, you will be moved up in the schedule and contacted for access. Payment may be held in escrow, if needed.

- ✓ We warranty mold remediation for 5 years!





Ness LLC

1315 W. Orchard Ave, Nampa, ID 83651
phone 208.466.7594 - fax 208.461.9505 - RCE-481
email: doug@nessllc.com - www.nessllc.com



Linda Evans, 208-949-7627
linda.evans@windermere.com

4-16-2020

Page 2 of 4

PROPOSED REMEDIATION at 7910 W. Tarp Dr. Boise, Idaho 83709

Ness, LLC is an IICRC council certified Mold Remediation Contractor, licensed, bonded, and insured with mold and environmental pollution endorsements.

As requested, the crawlspace and attic were inspected for water damage and mold. There does not appear to be any drainage issues, at this time. This is not a guarantee that there cannot be future water intrusion if conditions change. There appears to be sporadic mold throughout the crawlspace on the rim joist, floor decking, floor joists, and the area under the bath tub where there was a previous leak.

This will need to be remediated. The insulation was installed incorrectly and is falling down in a lot of areas. This will need to be removed before remediation and then replaced with R-30 insulation which is standard code in Idaho. The vapor barrier is in poor condition and needs to be replaced and pulled up onto the footings.

As for the attic, there appears to be sporadic microbial growth on the roof sheathing and top cords. The bath fan and laundry room fan need to be connected to roof jacks so they are venting properly to the exterior.

Part 1: Remove R-19 Insulation from the floor decking and dispose. Total Part 1: \$1,296.32

Part 2: Crawlspace Remediation:

1. All access to the crawlspace will be protected during work.
2. Containment will be set at the crawlspace access.
3. Hepa filtered negative air flow will be ongoing during the project.
4. The furnace system is to remain off during the work and for, at least, 3 hours after each treatment.
5. Move insulation, as needed, from area of remediation.
6. Surface cleaning and abrasive removal, as needed, of visible growth on impacted rim joist, floor decking, floor joists and framing under the bath tub. (See Part 3)
7. Put back removed insulation, as needed.

Part 3: Microbial Growth Remediation

1. After containment is set up, surface cleaning and abrasive removal will be performed, as needed, of visible microbial growth on the impacted areas. Once mold impacted surfaces are cleaned, then treat the remediated surfaces in the crawlspace with a non-toxic Microbial Growth Inhibitor.
2. (1) Procedures are established from IICRC S520 Standard and Reference Guide for Professional Mold Remediation. (2) All work in the crawlspace will be performed using accepted procedures. (3) Respiratory Protection is in accordance with the OSHA respiratory protection standard (29 CFR 1910.134) for the remediation. Gloves, full-face respirators, p-100 particulate filters, Tyvek full body suits with hoods and boots.
3. Photo documentation of work performed is available at the end of the project upon prior request. Disposal of debris.

Total Labor & Materials Parts 2-3: \$2,163.18

Part 4: Mandatory 3rd Party Certified mold inspector's visual inspection and documentation of the crawlspace, attic, and garage.
****Final Clearance Air testing not included in protocol or scope. ****

Part 4 Labor and Materials: \$370.00

Part 5: Install new R-30 batt insulation on the floor decking. (R-30 is code)

Part 5 Labor and Materials: \$1,932.08

Part 6: Remove and dispose of old vapor barrier, miscellaneous debris, and building materials. Install new 6 mil. vapor barrier in the entire crawlspace and pull up onto the footings, where possible.

Part 6 Labor and Materials: \$540.29

Ness LLC gives a **5 year limited warranty** on no visible microbial re-growth where work is done. Warranty is **void** if any water or water source introduced into the area.

Work under this proposal is limited to the items listed. Any additional work will need to be outlined and set out by a separate contract, or have the contract amended and signed to reflect any additional work desired.



Ness LLC

1315 W. Orchard Ave, Nampa, ID 83651
phone 208.466.7594 - fax 208.461.9505 - RCE-481
email: doug@nessllc.com - www.nessllc.com



Linda Evans, 208-949-7627

4-16-2020

Page 3 of 4

Part 7: Attic Remediation

1. All access to the attic will be protected during work.
2. Containment at the attic access will be set.
3. The furnace/AC system is to remain off during the work and for 3 hours after treatment.
4. Establish negative air flow. This will be ongoing while the work is performed.
5. Surface cleaning and abrasion removal, as needed and treat impacted roof sheathing and top cords. **(See Part 8)**
6. Seal penetrations that are accessible.
7. Add baffles, as needed.

Part 8: Microbial Growth Remediation

1. After containment is set up, surface cleaning and abrasive removal will be performed, as needed, of visible microbial growth on the impacted roof sheathing and top cords. Once mold impacted surfaces are cleaned, then treat the remediated surfaces in the attic with a non-toxic Microbial Growth Inhibitor.
2. (1) Procedures are established from IICRC S520 Standard and Reference Guide for Professional Mold Remediation. (2) All work in the attic will be performed using accepted procedures. (3) Respiratory Protection is in accordance with the OSHA respiratory protection standard (29 CFR 1910.134) for the remediation. Gloves, full-face respirators, p-100 particulate filters, Tyvek full body suits with hoods and boots.
3. Photo documentation of work performed is available at the end of the project upon prior request. Disposal of debris.

Total Labor & Materials Parts 7-8: \$3,226.18

Part 9: Ventilation

1. Install two roof jacks
2. Connect bath fan duct and laundry room duct to roof jacks.
3. Seal penetrations.

Part 9 Labor and Materials = \$248.00

Ness LLC gives a **5 year limited warranty** on no visible microbial re-growth where work is done. Warranty is **void** if any water or water source introduced into the area.

Work under this proposal is limited to the items listed. Any additional work will need to be outlined and set out by a separate contract, or have the contract amended and signed to reflect any additional work desired.



Ness LLC

1315 W. Orchard Ave, Nampa, ID 83651
phone 208.466.7594 - fax 208.461.9505 - RCE-481
email: doug@nessllc.com - www.nessllc.com



Linda Evans, 208-949-7627

4-16-2020

Page 4 of 4



Mold under improperly installed insulation



Mold under previous bath tub leak



Mold in attic where duct is not properly vented.

*>> Paid out of closing as long as closing is within 21 days of job completion or 50% down and 50% paid upon completion <<
>> 3% charge on credit card transactions <<*

Part 1 Accepted by: _____ Date _____

Parts 2-3 Accepted by: _____ Date _____

Part 4 Accepted by: _____ Date _____

Part 5 Accepted by: _____ Date _____

Part 6 Accepted by: _____ Date _____

Parts 7-8 Accepted by: _____ Date _____

Part 9 Accepted by: _____ Date _____

Please Indicate Payment Schedule: (check payment option) 50/50 Out of Closing

Please print name: _____

Ness (CMRS) -Idaho Contractor Registration# RCE-481

Ness LLC gives a **5 year limited warranty** on no visible microbial re-growth where work is done. Warranty is **void** if any water or water source introduced into the area.

Work under this proposal is limited to the items listed. Any additional work will need to be outlined and set out by a separate contract, or have the contract amended and signed to reflect any additional work desired.