



Caylee Ketchum, 208-860-3451 Ketz3961@gmail.com 8-6-2021

Page 1 of 1

RESTORATION PROPOSAL for the attic at 1110 Center Ave. Payette, Idaho

Ness, LLC is an IICRC council certified Mold Remediation Contractor, licensed, bonded, and insured with mold and environmental pollution endorsements.

As requested, the attic was inspected for mold. Remediation will be necessary as there appears to be sporadic microbial growth throughout the attic on the roof sheathing planks.

Other areas of concern that we inspected require demo so we will only be proposing remediation in the attic at this time.

Part 1: Attic Remediation

- 1. All access to the attic will be protected during work.
- 2. The furnace system is to remain off during the work and for 3 hours after each treatment.
- 3. Establish negative air flow. This will be ongoing while the work is performed.
- 4. Surface cleaning and abrasion removal, as needed and treat impacted roof sheathing. (See Part 2)
- 5. Install baffles as needed
- **6.** Install roof jack and connect bath fan duct to exhaust to the exterior.

Part 2: Microbial Growth Remediation

- 1. After containment is set up, then perform surface cleaning and abrasive removal as needed of visible microbial growth on the before mentioned affected areas. Once mold impacted surfaces are cleaned then, treat the remediated surfaces in the attic with a non-toxic Microbial Growth Inhibitor.
- 2. (1) Procedures are established from IICRC S520 Standard and Reference Guide for Professional Mold Remediation. (2) All work in the attic will be performed using accepted procedures. (3) Respiratory Protection is in accordance with the OSHA respiratory protection standard (29 CFR 1910.134) for the remediation. Gloves, full-face respirators, p-100 particulate filters, Tyvek full body suits with hoods and boots.
- 3. Photo documentation of work performed is available at the end of the project upon request before the start of the project.
- **4.** Disposal of debris.

Total Labor & Materials Parts 2-3: \$3,775.23

<u>Part 3:</u> Mandatory 3rd Party Certified mold inspector's visual inspection and documentation for the attic and bathroom.

Final Clearance Air Testing not included in protocol or scope

<u>ADD to Total \$210.00</u>

>> Paid out of closing if closing is within 21 days of job completion or 50% down and 50% paid upon completion << >> .53% charge on credit card transactions <<

Parts 1-2 Accepted by:	Date
Part 3 Accented by:	Date

Douglas A. Ness (CMRS) -Idaho Contractor Registration# RCE-481

Ness LLC give a <u>5-year limited warranty</u> on no visible microbial re-growth where work is done. Warranty is **void** if any water or water source introduced into the area. Work under this proposal is limited to the items listed. Any additional work will need to be outlined and set out by a separate contract, or have the contract amended and signed to reflect any additional work desired.